RICHARD HOUSE NC 258-24, east side, about Richlands Vicinity Onslow County North Carolina

HABS NC, 67-RZLAN,

PHOTOGRAPHS

WRITTEN HISTORICAL AND DESCRIPTIVE DATA

HISTORIC AMERICAN BUILDINGS SURVEY
NATIONAL PARK SERVICE
SOUTHEAST REGION
DEPARTMENT OF THE INTERIOR
ATLANTA, GEORGIA 30303


Form 10-920 (June 1983)


UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

HABS NC, 67-RILAY, 3-

ARCHITECTURAL DATA FORM

North Carolina	Onslow	Richlands	
HISTORIC NAME OF STRUCTURE Richard House	(INCLUOE SOURCE FOR NAME)	HABS NO. NC-371
SECONDARY OR COMMON NAME	S OF STRUCTURE		
COMPLETE ADDRESS (DESCRIBE NC 258-24, East Side,	E LOCATION FOR RURAL SITES) About 3,325' south of SR		e a T
DATE OF CONSTRUCTION (INCL Late 1930's (Venters I	_	HITECT(S) (INCLUDE SOURCE	<u>)</u>
SIGNIFICANCE (ARCHITECTURA Contributing Building	I <i>L AND HISTORICAL, INCLUOE C</i> in the Proposed Venters	1	RE)
STYLE (IF APPROPRIATE)			
MATERIAL OF CONSTRUCTION Wood, Frame SHAPE AND DIMENSIONS OF ST			ARE ACCEPTABLES
See Attached 1168 Squ	are Feet	LANS UN SEFANATE PAGES A	THE ACCEPTABLE
Tin Hipped Roof, 4-4 W	indows, Clapboard Siding		
INTERIOR FEATURES OF NOTE	(OESCRIBE FLOOR PLANS, IF NO	OT SKETCHEO)	
SEE ATTACHED FLOOR PLA	N		
MAJOR ALTERATIONS AND ADD	DITIONS WITH OATES		
	k, addition in rear; end after 1946 when the hou		ectangular wing.
PRESENT CONDITION AND USE Fair to Poor; Resident	ial, Single Family.		÷
OTHER INFORMATION AS APPR	OPRIATE		
SOURCES OF INFORMATION (IN			ERS, ETC.)
	ssistance Inspection Rep Case Report on Venters F		
COMPILER, AFFILIATION	•		DATE
Elizabeth Kirkland, N.	C. DOT Planning and Res	search	March 15, 1989





RICHARD HOUSE